



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D350-727-045
Job Sheet 187285



Part No: D350-727-045

Job Qty: 4 ea

Part Name: AS350/355 OEM Replacement Wearplates - Full-Length



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/29/18

Job Tracking No:

Due Date: 12/17/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: IIN D350-727 REV.B IPP Rev:A 05.05.12 New issue KJ/JLM IPP REV:B 12.04.11 AS PER ECN 12-546 DD
VERF:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	4 Ea		12/17/18	0.00	0.00	Start Up Stores/Pkg-1		DEC 28 2018
110	Packaging	4 pcs		12/17/18	0.00	0.00	Packaging1-3		DEC 28 2018
120	QC	4 pcs		12/17/18	0.00	0.00	QC4		69 DAS
130	Packaging	4 pcs		12/17/18	0.00	0.00	Packaging3-1		9-89 69
135	DC	4 pcs		12/17/18	0.00	0.00	DC		9-89
140	QC21-FG	4 Ea		12/17/18	0.00	0.00	QC21		DEC 31 2018

Part Op 130 - Identify and pack for shipping as per PPP D350-727-045 Location:FG041
Descriptions: 135 - Photocopy bluefile and create labels per PPP D350-727-045 CHG003

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D3319-1	Forward Wearplate	4 Ea (1 ea)	90-Start up Operation	5138490
D3319-3	Full Length Wearplate	4 Ea (1 ea)	90-Start up Operation	5127921

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D3319-1	4	15	0
	D3319-3	4	20	0

Part Specifications

Specifications could not be found.

Plex 11/29/18 1:40 PM Dart.lajeunesse.marie

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

Route update only ☐

NCR No. _____ Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large ☐ Cross tube ☐ Small ☐ Large ☐ (Non-AW) ☐ Ing. Coord. ☐ Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐		
Date : _____	Sequence #: _____	MRB (QSI042) _____		
Description Work Order _____		Completed By _____		
Lead hand / Supervisor _____		QC / QA Coordinator _____		
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐ ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread		Other/Details: _____ Container No: S140733 Part: D350-727-045 Job No: 187285 Serial No/Batch: S140733 Revision: B Inspector: _____ Exp Date: _____ Instructions: TC PDA PDA05-18 Issue 2 12/26/18		

Change Record

PAGE 1 OF 1

Part Number: D350-727-015/-045

Description: WEARPLATE, FULL LENGTH, LH/RH

[illegible]

